

ZDC-контейнеры и файлы

Все файлы доступные в программе VCP Вы можете скачать при помощи программы Активатор. Ниже приводится список доступных файлов разделенных по группам.

Актуальность на 17.01.2018

Access

4G0035082C_RMCRadio.zdc
5F_RMC_AudiA6.zdc
A1_DriverDoor_8x0959793b,d,e,f,g,h.zdc
A1_DriverDoor_8x0959793f,g,h.zdc
A1_passengerDoor_8x0959792b,d,e,f,g,h.zdc
a3_8v_eph.zdc
a3_8v_lwr_7p6907357b.zdc
A3_MQB_kessy.zdc
a3_mqb_pdc_5q0919283a,294b,298a.zdc
a3_mqb_pdc_5q0919283b,294c,294g,298b.zdc
a3_mqb_pdc_5q0919294a.zdc
a3_pdc_5q0919283D,E,294E,J,298F,G.zdc
a3_pdc_5q0919294x.zdc
a3_RFK_5q0907441.zdc
A4_A5_driverdoor_8t0959793F.zdc
A4_A5_driverdoor_8t0959793G.zdc
A4_A5_passdoor_8t0959792G.zdc
A4_A5_RearLeft_Doorcontrol_8t0959795F.zdc
A4_A5_RearRight_Doorcontrol_8t0959795F.zdc
A4_driverdoor_8t0959793J,K.zdc
A4FL_BCM1_8K0907063Ax,Dx.zdc
A4PA_BCM2_8k0907064Bx,CQ,Dx.zdc
A4PA_BCM2_8k0907064Cx.zdc
a4PA_bcm2_8k0907064Gx,Hx,Kx.zdc
A4PA_BCM2_8k0907065Ax,Bx,Cx,M,N.zdc
a5_bcm2_8k0907064Bx,Dx.zdc
A5_BCM2_8k0907064Cx.zdc
a5_bcm2_8k0907064Gx.zdc
A5_sportback_driverdoor_8t0959793G.zdc
A5_sportback_passdoor_8t0959792G.zdc
A5FL_BCM1_8K0907063Ax,Dx.zdc
a5PA_bcm2_4h0907064Gx,Hx,Jx.zdc
a6_acc_4g0907561a,b.zdc
A6_ACC_Master_4G0907561A,B.zdc
a6_bcm2_4h0907064Bx,Cx.zdc
a6_bcm_4h0907063Bx,Cx,g,h,j,m,n.zdc
a6_c7_imageProcessor_Camera_4g0907107e.zdc
A6_MXB_4H4907357D.zdc
a6_niveau_4g0907553f.zdc
a6_RFK_4s0907441,A,B.zdc
a6_sensorarray_4g0907637h,j,k,l.zdc
A7_8E_imageprocessor.zdc
A7_ACC_Master_4G0907561.zdc
A7_BCM2_4h0907064Bx,Cx,Dx,Ex.zdc
A7_driverdoor_4g8959793D,E.zdc
A7_passengerdoor_4g8959792D,E.zdc
A7_start_auth_4h0907064BP,BR,BT,DB,DC,Dx,Ex,Fx,Gx.zdc
A8_ACC_MASTER_4h0907561a.zdc
A8_ACC_MASTER_4h0907561B.zdc
a8_bcm1_4h0907063a,b,c,d,g,k.zdc

VAG-CAN PRO

a8_bcm1_4h0907063a,Bx,Cx,D,H,J,K,L.zdc
A8_MXB_4H4907357B.zdc
a8_niveau_4g0907553.zdc
a8_niveau_4g0907553B_4h0907553C,E,G.zdc
alhambra_5m0_xenon.zdc
AudiA6FL_AFS_4h4907357D.zdc
AudiTT_AFS_4h4907357D.zdc
B_O_8F1035223a_A5_cabrio.zdc
B_O_8T0035223AK_A5.zdc
B_O_8T0035223AN_A4_China.zdc
B_O_8T0035223AN_A5_FL.zdc
B_O_8T0035223f,h_A5.zdc
B_O_A4_8T0035223A,M,,N,O,Q.zdc
BO_A5_8T1035223A.zdc
BO_Amplifier_A6C7_4G0035465A,B,C.zdc
BO_Amplifier_A6C7_4G1035466.zdc
BOSE_A8_4G0035223C.zdc
BOSE_C7.zdc
BOSE_mmi2g_8t0035223F,g,m,r,t,Ax.zdc
BOSE_mmi3gp_8t1035223a.zdc
BOSE_Q7.zdc
CaddyGP_5M0_xenon.zdc
CAN_amplifier_8T0035223E,A,AB,AJ,B.zdc
discover_pro_5g0035020,021,043,045,046,050,819,820,824.zdc
dynaudio_CC_3aa035466.zdc
dynaudio_scirocco_5k0035456e.zdc
egolf7_AFS_5Q0907357.zdc
eos_dcc_3c0907376a.zdc
fender_beetle_3t0035456B,5c6035456,C.zdc
gateway_5q0907530Ax.zdc
gateway_5Q0907530530AD,AE,AF_golf.zdc
gateway_7n0907530an.zdc
gateway_7n0907530AT,BA,BB,BC.zdc
gateway_530F_golf_MQB.zdc
gateway_A4_8R0907468A,B,C,D,F,G,H,J,L,M,N,P.zdc
gateway_golf7_530R,S,T.zdc
gateway_q5_8r0907468e,f,g,h,j,k,l,m,n,p.zdc
golf7_acc_5q0907572A.zdc
golf7_AFS_7p6907357b.zdc
golf7_AFS_7p6907357d.zdc
golf7_cameraSTGA5_5q0980653C_sw032+.zdc
golf7_cameraSTGA5_5q0980653E_sw_50,51.zdc
golf7_cameraSTGA5_5q0980653f_sw_52.zdc
golf7_cameraSTGA5_5q0980653g.zdc
golf7_DriverDoor_5q0959393,A,593,A.zdc
golf7_driverdoor_5q0959393a.zdc
golf7_driverdoor_5q0959593b,c.zdc
golf7_driverdoor_5q4959593c.zdc
Golf7_kessy.zdc
golf7_passengerdoor_5q0959592a.zdc
golf7_passengerdoor_5q0959592b,c.zdc
golf7_passengerdoor_5q4959592c.zdc
golf7_pdc_5q0919283a_4ch.zdc
golf7_pdc_5q0919294e_europe.zdc
golf7_pdc_5q0919294f_europe.zdc
golf7_pdc_5q0919294f_japan.zdc
golf7_pdc_5q0919294x.zdc
golf7_pdc_5q0919298F.zdc
golf_dcc_3c0907376a.zdc

VAG-CAN PRO

jetta_xenon_5m0.zdc
leon_MQB_lwr_5q0907357.zdc
octavia3_AFS_7p6907357b.zdc
octavia3_mfk_5Q0980653E.zdc
octavia3_pdc_5q0919294x.zdc
octavia3_radar_5q0907572A.zdc
passat_5m0_xenon.zdc
passat_b7_5M0_xenon.zdc
passat_b7_cameraA5_3aa980654D.zdc
passat_b8_RFK_5q0980556.zdc
passat_b8_RFK_5q0980568.zdc
passat_bcm_3aa937087j.zdc
passat_cc_cameraA5_3aa980654D.zdc
passat_rearlid_5q0959107d,e.zdc
passat_tirepressure_5q0907273A,B.zdc
passatb8_pdc_5q0919294h.zdc
passatcc_5m0_xenon.zdc
passatCC_dcc_3c0907376_376a.zdc
phaeton_5M0_xenon.zdc
q5_bcm1_8k0907063Ax,Dx.zdc
q5_bcm2_8k0907064Bx,Dx.zdc
Q5_suspensioncontrol.zdc
Q5_suspensioncontrol_8k0907364a_sw0049.zdc
q5PA_bcm2_8k0907064Cx,Ex,Fx,Gx,Hx,Jx.zdc
RadioUnit_A4_4G0035061.zdc
RadioUnit_A4_4G0035061M.zdc
RadioUnit_Q5_.zdc
sharan_5m0_xenon.zdc
sharan_dcc_3c0907376a.zdc
SuperbII_5m0_xenon.zdc
T5GP_6R0907357_xenon.zdc
tiguan_cameraA5_3aa980654D.zdc
tiguan_tirepressure_3aa907273b,c,d.zdc
tiguan_tirepressure_3aa907273f.zdc
tiguanGP_5M0_xenon.zdc
Touareg_8E_imageprocessor.zdc
touareg_bcm2_4h0907064CK,DK,EK,FK.zdc
touareg_imageProcessor_Camera_7P6907107x.zdc
touareg_lwr_7p6907357.zdc
touareg_lwr_7p6907357c.zdc
touran_5m0_xenon.zdc
touran_xenon_5m0907357F.zdc
touranGP_5M0_xenon.zdc

BCM2

A4_BCM2_8k0907064Ax,c,d,e,f,g,h,j,l,m,n,p,q,r,s,t.zdc
A4_bcm2_8k0907064Bx,Dx.zdc
a4PA_bcm2_8k0907064Gx,Hx,Jx,Kx.zdc
A4PA_gateway_8r0907468A,b,c,d,f,g,h,j.zdc
a5PA_start_auth_8K0907064Cx,Kx.zdc
A6_start_auth_4H0907064Fx.zdc
A7_bcm2_4h0907064Ax.zdc
A7_start_auth_4h0907064CR,CT,CP.zdc

VAG-CAN PRO

BCM2N

a4_start_auth_8K0907064.zdc
a4FL_start_auth_8K0907064.zdc
A6_start_auth_4H0907064Ax,Bx,Cx,Dx.zdc
q5PA_start_auth_8K0907064Cx,Kx.zdc

COMMON

MEM_PATCH_TEMPLATE.mempatch
passatcc_3aa937087j_lampconfigeep.mempatch
scirocco_5k0937087AB,AD,086R_lampconfigeep.mempatch
superbII_lampconfigeep.mempatch
VAS_6350.pdf

FlashUpgrades

4F0910279GtoN.cry
4F0910279K_H15_S0240.cry
4F1910401B__0060_manual.cry
4H0907063__0130.cry
4L0910468A__0071.cry
5Q0919298D__0042.flash
7N0907530AN_1642.cry
7N0907530BG_1671.cry
FL_4G0907160B__0007.flash
gateway_flashes.rar
modded_files.zip
RG3_ECE_0350.rar

MMI3G

4H_MMI3GP.zdc
A3_MQB_MMI_8v0035020.zdc
A4_MMI3G_STANDARD.zdc
a4_MMI3GP.zdc
A8_MMI3GP_SW614+.zdc
leon_5F_5F0035020,A,043,A,869C.zdc
leon_5F_5F0035824A,834A,846A,848,850,858.zdc
q5_mmi3gp_8f1035666,670,8r1035746x.zdc
q7_MMI3GP.zdc
RNS850_670F.zdc

Newest Files

5F_RMC_AudiA1,Q3.zdc
A3_MIB_8v0035864A.zdc
A3_MQB_MMI_8v0035020B_J,021A_C,024,A,B,026A,B,032,A_C,034,A_E,035,A_F,036,A_F,038,A_C
,039A_B,043B_J.zdc
a3_mqb_pdc_5q0919283f,294k,298k.zdc
A3_powersteering_maps_5q0909144S.zdc
a3_soundsystem_8v0035465A.zdc
A4_powersteering_8k0909144f.zdc
A4PA_gateway_8r0907468A_P.zdc

VAG-CAN PRO

A4PA_gateway_8r0907468AA.zdc
A4PA_sportdiff_8k0907163B.zdc
A4PA_start_auth_8K0907064Jx.zdc
A5_BCM1_8k0907063E,F,G,H,I,J,BE,CC,CE.zdc
a5_bcm2_8k0907064DG.zdc
a6_bcm2_4h0907064Fx,Gx.zdc
A6_c7PA_RMC_4g0035193f.zdc
A6_MXB_4H4907357E.zdc
a6_niveau_4g0907553b.zdc
a6_niveau_4g0907553g.zdc
A6FL_BCM1_4h0907063AG,AK,DF,DG,DH,DK,DM.zdc
A6FL_BCM1_4h0907063DK.zdc
A6FL_MIB_4g1035020,021.zdc
A7_LaneChangeAssist_4g0907566M,4H0907566f,566e.zdc
A8_4h_imageProcessor_Camera_4g0907217,4h0907217A,B.zdc
a8_bcm2_4h0907064Bx,Cx,Dx,Ex.zdc
a8fl_gateway_4h0907468ae.zdc
audiTT_pdc_5q0919283E,294J,G.zdc
BO_8T0035223AN_Q5_FL.zdc
caddy4_pdc_1k8919465.zdc
eos_kessy_5k0959434a.zdc
fabia_pdc_5q0919294E.zdc
golf7_pdc_5q0919294k.zdc
golf7_powersteering_maps_5q0909144L,M.zdc
golf7_radar_5q0907572G.zdc
golf7_rearradar_5Q0907686A.zdc
golf_drivdoor_5q4959592E.zdc
golf_passdoor_5q4959592E.zdc
Heckradar_q7_4m0907566.zdc
leon_5F_5F0035824,834,846,858.zdc
leon_5F_5qa035824.zdc
leon_5F_5qa035858.zdc
leon_cameraSTGA5_5q0980653g.zdc
MIB2_polo_3q003581x,82x,84x,86x,87x,6c003586x.zdc
octavia3_AFS_7p6907357d.zdc
octavia3_dcc_5q0907376.zdc
octavia3_kessy_5q0959435a,b.zdc
octavia_dynamicsteering_maps_3q0909144d.zdc
octavia_powersteering_maps_5q0909144l.zdc
octavia_rear_lid_5e0959107a.zdc
octavia_rfk_5q0980556.zdc
passat_areaview_5q0907556.zdc
passat_cc_SteeringWheel_5k0953569AS.zdc
passat_frontcamera_3q0980653d.zdc
passat_frontcamera_3q0980653e.zdc
passat_frontcamera_3q0980654c.zdc
passat_frontcamera_3q0980654f.zdc
passat_tirepressure_3aa907273h.zdc
passatCC_RFK_7n0907441B.zdc
q3_55_LED_5m0907357g.zdc
Q5_BCM2_8K0907064Hx,Jx,Kx.zdc
q5_dcc_8r0907364B.zdc
q5_radiounit_4g1035053G.zdc
Q5FL_BCM1_8K0907063Ax,Dx.zdc
Q7_RFK_4M0980556.zdc
Q7_RFK_4M0980568.zdc
RadioUnit_A4_4g003505x,061,A_Q.zdc
RadioUnit_A4_4g0035053C.zdc
RadioUnit_q5_4f0035056a.zdc

VAG-CAN PRO

sharan_pdc_7n0919475E.zdc
superb3_dcc_5q0907376.zdc
superb3_DriverDoor_5q0959393B,593A.zdc
superb3_PassDoor_5q0959392B,592A.zdc
Superb3_pdc_5q0919298C_L.zdc
Superb3_pdc_5qa919298.zdc
touareg_tirepressure_7p6907273h.zdc
yeti_xenon_5m0907357F.zdc

PRCoder

a3_BCM_5q0937085S.prc
BCM_a3_5q0937085r,s,t,084ab,ac,ad,ae.prc
bcm_octavia_5q0937084AG.prc
MIB_high_GEN2_skoda_3g003502x.prc
MIB_high_GEN2_skoda_3v00350xx.prc
pr_pak.rar

Q1 2016

4m0907379ac_ad_params.zip
a3_limo_driverdoor_5q0959593e.zdc
a3_limo_passengerdoor_5q0959592e.zdc
a3_lwr_7p6907357c.zdc
a3_pdc_5qa919283.zdc
a3_pdc_5qa919294.zdc
a3_rfk_5q0980556b.zdc
a4_8w0907217b_camera.zip
a4_b8_LaneChangeAssist_8t0907566.zdc
a4_BCM2_8w0907064aa.zdc
a4_camera_8w0907217a_FlashDatasets.zip
a5_8w6907217_ds.zip
a5_RFK_4M0980556a.zdc
a6_c7_imageProcessor_Camera_4g0907107b.zdc
a6_c7_imageProcessor_Camera_4g0907107d.zdc
a6_imageProcessor_8e_4h0907107f,g.zdc
a6_imageProcessor_8e_4h0907107h.zdc
A6_powersteering_4g0909144l.zdc
a6_sportdiff_4h0907163a.zdc
A6FL_BCM2_4h0907064DB,DD,DF,DH,Ex,Fx.zdc
A6FL_imageProcessor_Camera_4h0907217F.zdc
a6pa_MMI_4g1035020,A_F,021,A_F,024,025.zdc
A7_bcm2_4h0907064fr.zdc
A8_4h_imageProcessor_Camera_85_4h0907217A_model2010.zdc
A8_MXB_4H4907357E.zdc
a8_niveau_4g0907553g.zdc
a8_niveau_4h0907553B.zdc
a8_sportdiff_4h0907163a.zdc
acc_leon_5q0907572H.zdc
acc_leon_5q0907572J.zdc
acc_superb_3q0907572b.zdc
AudiTT_AFS_4h4907357D_sw0081.zdc
BCM1_a4_8w0907063ab,ac.zdc
BCM2_a4_8w0907064AL.zdc
BCM2_a4_8w0907064bc.zdc
BCM2_q7_8w0907064cd.zdc
belttensioner_left_a6_4h0980945.zdc

VAG-CAN PRO

belttensioner_right_a6_4h0980946.zdc
BO_A4_8T1035223A.zdc
BO_MIB2_Amplifier_A6C7_4G1035466C.zdc
BO_MIB2_Amplifier_A6C7_4G1035466C_sw586.zdc
BOSE_A6_4g9035223d.zdc
BOSE_A7_4g0035223c.zdc
BOSE_A7FL_4g5_8_035223A,B,C.zdc
BOSE_q7_4L0035223J.zdc
BOSE_q7_4m0035223a.zdc
caddy_5k0937087ac_lampconfigeep.mempatch
decklid_superb_5q0959107J_model2017.zdc
decklid_superb_5q0959107J_model_q4_2016.zdc
fabia_pdc_5q0919283f.zdc
gateway_leon_5q0907530AJ_2016.zdc
gateway_leon_5q0907530AJ_2017.zdc
golf6_driverdoor_5k0959701e.zdc
golf7_AFS_5Q0907357.zdc
golf7_radar_5q0907541J.zdc
golfsportsvan_driverdoor_5q0959593d.zdc
heckdeckel_touran_5q0959107J.zdc
heckradar_q7_4m0907566b.zdc
jetta_pdc_1k8919472A.zdc
jetta_pdc_1kd919472A.zdc
jetta_rearradar_5Q0907686B.zdc
jetta_xenon_5m0907357F.zdc
MIB_5c0035680x.zdc
octavia3_AFS_7p6907357a.zdc
octavia3_pdc_5q0919294k.zdc
octavia3_pdc_5q0919298D.zdc
octavia_ACC_5q0907572H.zdc
octavia_driverdoor_5q4959593B.zdc
Octavia_mqb_pdc_5q0919283f.zdc
octavia_passdoor_5q4959592B.zdc
octavia_pdc_5q0919298k.zdc
octavia_rearradar_5q0907686B.zdc
octavia_RFK_5q0980568A.zdc
passat_frontcamera_3q0980654g.zdc
passatcc_pdc_1k8919475B.zdc
passatcc_pdc_1k8919475d.zdc
passatcc_pdc_1k8919475e.zdc
passatCC_tirepressure_3aa907273d.zdc
polo_lwr_6R0907357c.zdc
polo_passat_greentrainer_repair.zdc
q5_80a907217_ds.zip
Q5_gateway_8r0907468R,S,T,AA.zdc
q5_LaneChangeAssist_8t0907566b.zdc
q5_RFK_4M0980556a.zdc
q7_areaview_4m0907428d.zdc
q7_camera_4m0907217c_FlashDatasets.zip
q7_camera_4m0907217d_FlashDatasets.zip
q7_lightcontroller_leftd6_7pp941592c.zip
q7_lightcontroller_rightd7_7pp941592c.zip
q7_powersteering_4m0909144e.zdc
q7nf_bcm1_8w0907063e.zdc
q7nf_bcm2_8w0907064bh.zdc
RadioUnit_a6c6_4G0035061P.zdc
RDK_q7_4m0907273b.rar
rearlid_passat_5q0959107g.zdc
rearlid_passat_5q0959107j.zdc

VAG-CAN PRO

rearlid_tiguan_5q0959107g.zdc
scirocco_xenon_5m0907357F.zdc
sharan_acc_7n0907572a.zdc
sharan_pdc_1k8919475B.zdc
superb3_rfk_5q0980556b.zdc
superb_decklid_5q0959107g.zdc
superb_decklid_5q0959107g_autoclose_test.zdc
superb_rearlid_5q0959107e.zdc
superb_rearlid_5q0959107e_autoclose.zdc
superb_rfk_5q0980556.zdc
tiguan_areaview_5q0907556a.zdc
tiguan_areaview_5q0907556b.zdc
tiguan_frontcamera_3q0980654g.zdc
tiguan_pdc_1k8919475d.zdc
tiguan_pdc_3q0919294.zdc
tiguan_pdc_3q0919298.zdc
tiguan_pdc_3q0919298A.zdc
tiguan_pdc_3q0919294.zdc
tiguan_rfk_5q0980556b.zdc
touran_pdc_5qa919298.zdc
touran_RFK_5q0980568A.zdc
tt_pdc_5q0919294k.zdc

Q1 2017

7P5941572A_DS.zip
8v0907399D_golfE.zip
a1_rfk_81A827566a.zdc
a3_acc_5q0907572g.zdc
a3_cameraSTGA5_5q0980653g.zdc
a3_frontcamera_3q0980654g.zdc
a3_frontcamera_3q0980654h.zdc
a3_lwr_7p6907357d.zdc
A3_MIB_8v0035036.zdc
A3_MXB_8v0907357A.zdc
a3_pdc_5qa919294b.zdc
a3_powersteering_maps_5q0909144t_pgrsv_3q0909144K,L.zdc
a3_radar_5q0907572A.zdc
a3_RFK_5q0907441a.zdc
A3FL_AudioSettings_MMI_81a035824,B.zdc
a4_4m0907397ac_lcm.zip
A4_7PP941571BC.zip
a4_8w0907217C.zip
a4_b8_LaneChangeAssist_8t0907566a.zdc
A4_B9_mib2_8w0035039x,035x.zdc
a5_LaneChangeAssist_8t0907566a.zdc
A5_VZE_a4_cabrio_8w7907217.zip
A6_LaneChangeAssist_4g0907566M.zdc
a6_niveau_4g0907553c.zdc
A7_driverdoor_4g8959793j.zdc
A7_MXB_4H4907357E.zdc
a7_niveau_4g0907553b.zdc
A7_passdoor_4g8959792j.zdc
a8_acc_4h0907561c.zdc
A8_LaneChangeAssist_4g0907566f.zdc
a8_niveau_4h0907553E_sw0099.zdc
amp_a3_81a035466,a,b.zdc
BCM2_q5_8w0907064dh.zdc
BCM2_s5_8w0907064dc.zdc

VAG-CAN PRO

BOSE_A1_8X0035223c.zdc
BOSE_A6_4g0035223a.zdc
BOSE_A6_4g0035223B,C.zdc
BOSE_A6_4g1035223A.zdc
BOSE_A6FL_4g5_8_035223B.zdc
BOSE_A7_4g0035223a.zdc
BOSE_q7_4m0035223c.zdc
golf7_radar_5q0907572B.zdc
golf_fcm_3q0907338.zdc
golf_frontcamera_3q0980654a.zdc
golf_frontcamera_3q0980654g.zdc
golf_frontcamera_3q0980654h.zdc
golfe_fcm_3q0907338.zdc
Heckradar_a3_3q0907566c.zdc
keyless_BCM2_a4_8w0907064ch.zdc
leon_fcm_3q0907338.zdc
leon_frontcamera_3q0980654g.zdc
leon_pdc_5qa919294a.zdc
leon_powersteering_maps_5q0909144s.zdc
octavia_cameraSTGA5_5q0980653g.zdc
octavia_driverdoor_5q4959593E.zdc
octavia_frontcamera_3q0980654g.zdc
octavia_frontcamera_3q0980654h.zdc
octavia_passdoor_5q4959592E.zdc
octavia_pdc_5qa919298b.zdc
octavia_pdc_5qa919298c.zdc
octavia_powersteering_maps_5q0909144s.zdc
octavia_powersteering_maps_5q0909144t.zdc
octavia_rfk_5q0980556b.zdc
passat_b8_7p6907357c.zdc
passat_frontcamera_3q0980654h.zdc
passatcc_3aa937087j_lampconfigeep.mempatch
Q3_rmc_8u1035183d.zdc
q5_areaview_4m0907428e.zdc
Q5_sportdiff_8k0907163B.zdc
q7_areaview_4m0907428e.zdc
R8_MXB_4H4907357F,G.zdc
rear_lid_passat_5q0959107j.zdc
rear_lid_passat_5q0959107L.zdc
superb_pdc_5qa919298b.zdc
superb_pdc_5qa919298c.zdc
superb_rearradar_5Q0907686B.zdc
tiguan_frontcamera_3q0980654h.zdc
touran_frontcamera_3q0980654h.zdc
touran_pdc_5qa919298b.zdc
touran_pdc_5qa919298c.zdc

VAG-CAN PRO

VIM

A1_mmi3g_VIM.zdc
A1_rmc_VIM.zdc
A3_MQB_SMALL_MMI_VIM.zdc
A3_MQB_VIM.zdc
A3_MQB_VIM_DEF.zdc
GOLF_VII_DISC_PRO_VIM.zdc
GOLF_VII_DISC_PRO_VIM_DEF.zdc
Leon_5F_navi_standard_VIM.zdc
MMI3GP_A4_A6_A7_A8_VIM.zdc
octavia_III_amundsen_VIM.zdc
RNS850_670F_VIM.zdc
Skoda_octavia3_columbus_VIM.zdc

VIMN - доступны только с активной функцией VIM

A4_8w_VIM.zdc
A6_A7_FACELIFT_VIM.zdc
A6_A7_FACELIFT_VIM_deact.zdc
A6_A7_FACELIFT_VIM_V2.zdc
AudiTT_8S0_VIM.zdc
GOLF_VII_DISC_PRO_VIM_DAB.zdc
Leon_5F_navi_small_VIM.zdc
MQB_MIBGen2_3G0_VIM.zdc
MQB_MIBGen2_3v0_VIM.zdc
PASSAT_B8_DISC_PRO_VIM.zdc
PASSAT_B8_DISC_PRO_VIM_V2.zdc
polo_6c_mib_gen2_3q0_VIM.zdc
POLO_FL_DISC_PRO_VIM.zdc
Q7_II_VIM.zdc
superb3_columbus_vim.zdc
transporter_t6_mib_VIM.zdc

Россия, Санкт-Петербург, наб. Обводного канала 118А

Телефон: +7981 728 9637

info@vagcanpro.ru

www.vag-ecu.ru

www.vagcanpro.ru